



# **AirCard Watcher**

## **Release Notes**

### **Build 3375**

Copyright © 2011 - 2012 Sierra Wireless, Inc.

This document contains information which is proprietary and confidential to Sierra Wireless, Inc. Disclosure to persons other than the officers, employees, agents, or subcontractors of the Company or licensee of this document without the prior written permission of Sierra Wireless, Inc. is strictly prohibited.

Document #:		Revision:	Build 3375	Page 2 of 19
-------------	--	-----------	------------	--------------

## Table of Contents

1	General.....	3
1.1	Purpose.....	3
1.2	General.....	3
1.3	Installing or upgrading AirCard Watcher.....	3
1.4	Summary of Revision History.....	4
2	Revision History .....	5
2.1	Build 3375 .....	5
2.2	Build 3355 .....	5
2.3	Build 3331 .....	6
2.4	Build 3285 .....	7
2.5	Build 3253 .....	8
2.6	Build 3211 .....	9
2.7	Build 3196 .....	10
2.8	Build 3092 .....	11
2.9	Build 3039 .....	12
2.10	Build 2982 .....	13
2.11	Build 2964 .....	15
2.12	Build 2838 .....	17
2.13	Build 2805 .....	18

Document #:		Revision:	Build 3375	Page 3 of 19
-------------	--	-----------	------------	--------------

## 1 General

---

### 1.1 Purpose

This document is intended to capture technical changes to the AirCard Watcher software release package.

These release notes are NOT intended for the end user.

A new revision of this document will be issued when any of the components of the AirCard Watcher product are updated.

### 1.2 General

The Build number is a Sierra Wireless assigned number that uniquely identifies all external releases of software and firmware. It is not specific to a product or software revision. It is an internal reference only.

### 1.3 Installing or upgrading AirCard Watcher

- If you have a previous version of AirCard Watcher you should uninstall it first:
  - o Go to Control Panel and select “Add or Remove Programs”
  - o Select “Sierra Wireless AirCard Watcher” and click on “Uninstall”
- Launch the Watcher installation package and follow the onscreen installation instructions.

## SIERRA WIRELESS, INC.

Document #:		Revision:	Build 3375	Page 4 of 19
-------------	--	-----------	------------	--------------

### 1.4 Summary of Revision History

Date	Build
March 02 <sup>nd</sup> , 2012	Build 3375
January 27 <sup>th</sup> , 2011	Build 3355
December 16 <sup>th</sup> , 2011	Build 3331
November 25 <sup>th</sup> , 2011	Build 3285
October 12 <sup>th</sup> , 2011	Build 3253
August 30 <sup>th</sup> , 2011	Build 3211
August 15 <sup>th</sup> , 2011	Build 3191
June 17 <sup>th</sup> , 2011	Build 3092
June 3 <sup>rd</sup> , 2011	Build 3039
April 13 <sup>th</sup> , 2011	Build 2982
March 18 <sup>th</sup> , 2011	Build 2964
December 10, 2010	Build 2838
November 19, 2010	Build 2805

Document #:		Revision:	Build 3375	Page 5 of 19
-------------	--	-----------	------------	--------------

## 2 Revision History

---

### 2.1 Build 3375

#### 2.1.1 Component List

Description	Component	Revision
Watcher Main Application	Watcher.exe	12.0.1202.1
QMI SDK	GobiApi.dll	2.5.1202.3
Card Detect	SwiCardDetectX.dll	11.3.1201.0
MSI Installer	*.msi	6.0.3375

#### 2.1.2 Change Details

- [B41033](#): APN updates in Watcher are now reflected in Windows UI
- [B38394](#): SMS outbox messages can now be saved
- [B39414](#): Deregistration state correctly updated
- [B39047](#): Fixed crash after SIM switching
- [B39049](#): Fixed crash after restart with invalid profile
- [B40702](#): Display configuration profiles (IMS, GPS, etc) in advanced mode
- [B39314](#): Manual network configuration enabled for MC7750
- [B39358](#): GPS configuration enabled for MC7750

#### 2.1.3 Supported devices:

- Gobi 3000
- MC7700
- MC7710
- MC7750

#### 2.1.4 Known Issues

- Device drivers are not included and must be installed separately

### 2.2 Build 3355

#### 2.2.1 Component List

Description	Component	Revision
Watcher Main Application	Watcher.exe	12.0.1201.2
QMI SDK	GobiApi.dll	2.4.1201.4
Card Detect	SwiCardDetectX.dll	11.3.1112.1
MSI Installer	*.msi	6.0.3355

Document #:		Revision:	Build 3375	Page 6 of 19
-------------	--	-----------	------------	--------------

### 2.2.2 Change Details

- [B39993](#): Fixed rare crash after shutdown
- [B40079](#): Fixed rare hang after disabling Airplane mode
- [B40015](#): No longer display incorrect band info under advanced menu
- [B39881](#): Added support for MS assisted GPS
- [B39882](#): Added support for MS based GPS
- [B40162](#): Missing leading zeros from GPS data
- [B40052](#): Updated profile automation behaviour
- [B40112](#): Settings correctly updated when modifying the default profile

### 2.2.3 Supported devices:

- Gobi 3000
- MC7700
- MC7710
- MC7750 (Beta)

### 2.2.4 Known Issues

- Device drivers are not included and must be installed separately

## 2.3 Build 3331

### 2.3.1 Component List

Description	Component	Revision
Watcher Main Application	Watcher.exe	12.0.1112.1
QMI SDK	GobiApi.dll	2.3.1112.2
Card Detect	SwiCardDetectX.dll	11.3.1112.0
MSI Installer	*.msi	6.0.3331

### 2.3.2 Change Details

- [B39317](#): Japanese localization updates
- [B37533](#): Preserve network selection mode
- [B39178](#): Speed graph unit correction
- [B39309](#): Profile management updates
- [B38926](#): Removed frequency band display from Help->About
- [B39213](#): Sync signal bars after resume from S3
- [B39212](#): Signal strength indicator improvements
- [B39029](#): Close application on disconnect functionality now works
- [B39173](#): Profile UI updates
- [B39175](#): Added prompt for APN

### 2.3.3 Supported devices:

- Gobi 3000

## SIERRA WIRELESS, INC.

Document #:		Revision:	Build 3375	Page 7 of 19
-------------	--	-----------	------------	--------------

- MC7700
- MC7710
- MC7750 (Beta)

### 2.3.4 Known Issues

- Device drivers are not included and must be installed separately

## 2.4 Build 3285

### 2.4.1 Component List

Description	Component	Revision
Watcher Main Application	Watcher.exe	12.0.1111.0
QMI SDK	GobiApi.dll	2.3.1111.2
Card Detect	SwiCardDetectX.dll	11.3.1111.1
MSI Installer	*.msi	6.0.3285

### 2.4.2 Change Details

- [B37504](#): Network indicator improvements
- [B37507](#): LTE signal strength indicator improvements
- [B37746](#): RF band indicator improvements
- [B37911](#): Auto connect improvements
- [B38591](#): SIM detection improvements
- [B37388](#): Improvements to automatic firmware switching feature
- [B37780](#): Report correct error when connecting with invalid APN on Windows 7
- [B38117](#): Report CDMA dormancy state in tooltip
- [B37884](#): Fixed auto launch browser feature
- [B37895](#): Added installer option to configure Watcher auto-launch functionality
- [B38318](#): Watcher no longer prompts to create default profile when using MC7750
- [B37269](#): Added support for MEP lock state
- [B35412](#): Fixed GPS Monitor device detection issue
- [B37894](#): Added UI option to configure GPS One XTRA
- [B38636](#): Report correct number of satellites in GPS Monitor
- [B38635](#): Data usage history improvements

### 2.4.3 Supported devices:

- Gobi 3000
- MC7700
- MC7710
- MC7750 (Alpha)

## SIERRA WIRELESS, INC.

Document #:		Revision:	Build 3375	Page 8 of 19
-------------	--	-----------	------------	--------------

### 2.4.4 Known Issues

- Device drivers are not included and must be installed separately (Driver Build 3307 or newer is recommended).

## 2.5 Build 3253

### 2.5.1 Component List

**Changes between this version and the previous one are highlighted in blue.**

Description	Component	Revision
Watcher Main Application	Watcher.exe	12.0.1109.0
QMI SDK	GobiApi.dll	2.1.1108.2
Card Detect	SwiCardDetectX.dll	11.3.1108.4
MSI Installer	*.msi	6.0.3253

### 2.5.2 Change Details

- [B36990](#): Fixed issue which prevented firmware switching on some platforms

### 2.5.3 Supported devices:

- Gobi 3000
- MC7700
- MC7710
- MC 7750 (Evaluation purposes only)



Document #:		Revision:	Build 3375	Page 9 of 19
-------------	--	-----------	------------	--------------

## 2.6 Build 3211

### 2.6.1 Component List

**Changes between this version and the previous one are highlighted in blue.**

Description	Component	Revision
Watcher Main Application	Watcher.exe	12.0.1108.3
QMI SDK	GobiApi.dll	2.0.1108.2
Card Detect	SwiCardDetectX.dll	11.3.1108.4
MSI Installer	*.msi	6.0.3211

### 2.6.2 Change Details

- [B36134](#): Generic QMI Watcher installer includes QMI Drivers
- [B34300](#): Watcher composes received concatenated SMS messages
- [B35414](#): GPS monitor displays Altitude
- [B36177](#): GPS Monitor displays Speed and Direction

### 2.6.3 Supported devices:

- Gobi 3000
- MC7700
- MC7710
- MC7750 (Evaluation purposes only)

Document #:		Revision:	Build 3375	Page 10 of 19
-------------	--	-----------	------------	---------------

## 2.7 Build 3196

### 2.7.1 Component List

**Changes between this version and the previous one are highlighted in blue.**

Description	Component	Revision
Watcher Main Application	Watcher.exe	<a href="#">12.0.1108.2</a>
QMI SDK	GobiApi.dll	<a href="#">2.1.1108.1</a>
Card Detect	SwiCardDetectX.dll	<a href="#">11.3.1108.2</a>
MSI Installer	*.msi	<a href="#">6.0.3196</a>

### 2.7.2 Change Details

- [B35610](#) The 'SidebySide' error resolution
- [B35803](#) Modify long Japanese text message to fit on the GUI
- [B35805](#) Watcher installation on Guest/System user account

### 2.7.3 Supported devices:

- Gobi 3000
- MC7700
- MC7710
- MC7750 (Evaluation purposes only)

### 2.7.4 Known Issues

- Device drivers are not included and must be installed separately

Document #:		Revision:	Build 3375	Page 11 of 19
-------------	--	-----------	------------	---------------

## **2.8 Build 3092**

### **2.8.1 Component List**

**Changes between this version and the previous one are highlighted in blue.**

<b>Description</b>	<b>Component</b>	<b>Revision</b>
Watcher Main Application	Watcher.exe	<a href="#">12.0.1106.2</a>
QMI API	GobiApi.dll	<a href="#">2.0.1106.1</a>
CNS API	SwiApiInterfaceX.dll	<a href="#">11.4.1106.3</a>
Card Detect	SwiCardDetectX.dll	<a href="#">11.3.1105.1</a>
Watcher UI	WaUI.dll	<a href="#">11.3.1105.1</a>
QMI Plug-in	QmiPlugin.dll	<a href="#">12.0.1106.1</a>
MSI Installer	*.msi	<a href="#">6.0.3092</a>

### **2.8.2 Change Details**

- [B33501](#): Added network preference selection
- [B32604](#): Added advanced Help->About information
- [B33470](#): Firmware selection option no longer disabled
- [B34118](#): Correctly display current frequency band

### **2.8.3 Supported devices:**

- Gobi 3000
- MC7700
- MC7710
- MC7750 (Evaluation purposes only)

### **2.8.4 Known Issues**

- Device drivers are not included and must be installed separately
- Online Help localization incomplete
- Network selection and USB interface management not supported
- DUN connections not supported
- Auto launch application on data connection not supported

## SIERRA WIRELESS, INC.

Document #:		Revision:	Build 3375	Page 12 of 19
-------------	--	-----------	------------	---------------

### 2.9 Build 3039

#### 2.9.1 Component List

**Changes between this version and the previous one are highlighted in blue.**

Description	Component	Revision
Watcher Main Application	Watcher.exe	12.0.1105.5
QMI API	GobiApi.dll	1.2.1104.2
CNS API	SwiApiInterfaceX.dll	11.4.1105.1
Card Detect	SwiCardDetectX.dll	11.3.1105.0
Watcher UI	WaUI.dll	11.3.1105.0
QMI Plug-in	QmiPlugin.dll	12.0.1105.1
MSI Installer	*.msi	6.0.3039

#### 2.9.2 Change Details

- [B32439](#): Correctly save profile MCC/MNC
- [B31601](#): Improved data connectivity after suspend/resume
- [B31468](#): Improved data connectivity on LTE network
- [B31521](#): Improved manual network selection
- [B31602](#): Timeout waiting to terminate a data session increased from 8 seconds to 60 seconds
- [B31853](#): Fixed rare crash during modem insertion
- [B31477](#): Fixed rare crash during modem removal
- [B31643](#): Added SMS storage options
- [B33116](#): GPS monitor correctly detects modem

#### 2.9.3 Supported devices:

- Gobi 3000
- MC7700
- MC7710
- MC7750 (Evaluation purposes only)

#### 2.9.4 Known Issues

- Device drivers are not included and must be installed separately
- Online Help localization incomplete
- Network selection and USB interface management not supported
- Advanced Help->About UI not supported
- DUN connections not supported
- Auto launch application on data connection not supported

## SIERRA WIRELESS, INC.

Document #:		Revision:	Build 3375	Page 13 of 19
-------------	--	-----------	------------	---------------

### 2.10 Build 2982

#### 2.10.1 Component List

**Changes between this version and the previous one are highlighted in blue.**

Description	Component	Revision
Watcher Main Application	Watcher.exe	<a href="#">12.0.1103.5</a>
QMI API	GobiApi.dll	<a href="#">1.2.1104.0</a>
CNS API	SwiApiInterfaceX.dll	<a href="#">11.3.1104.0</a>
Card Detect Service	SwiCardDetect.exe	<a href="#">11.3.1104.0</a>
Card Detect	SwiCardDetectX.dll	<a href="#">11.3.1104.0</a>
Watcher UI	WaUI.dll	<a href="#">11.3.1103.0</a>
QMI Plug-in	QmiPlugin.dll	<a href="#">12.0.1103.6</a>
Watcher Helper Application	WaHelper.exe	<a href="#">11.3.1102.1</a>
MSI Installer	*.msi	<a href="#">6.0.2982</a>
Watcher Predefined Profiles	Predefined_Profiles.xml	1.56
SWLogCollector	SWLogCollector.exe	<a href="#">B2965</a>
AirCard Updates	TRUUpdater.exe	B2943

#### 2.10.2 Change Details

- [B29957](#): Added 3G/4G network service indicator
- [B30432](#): Added user option to manually invoke CDMA activation
- [B30799](#): CDMA network tab improvements
- [B31276](#): CDMA network icon improvements
- [B30640](#): Enable GPS menu even if no SIM attached
- [B30795](#): Auto-connect improvements
- [B30816](#): Roaming preference UI updates
- [B30287](#): "Operation Was Successful" no longer displayed when incorrect PIN2 is entered
- [B30305](#): PUK locked UI message improvements
- [B31217](#): PIN2 remaining attempts correctly displayed
- [B31223](#): PIN update message displayed in main window
- [B30576](#): Theme switching improvements
- [B30577](#): Roaming icon updates
- [B30753](#): Watcher icon shortcut updates
- [B30772](#): GPS monitor improvements
- [B30811](#): Profile improvements
- [B30934](#): Added configuration item to restrict connections while roaming
- [B30792](#): Data counter improvements
- [B30851](#): Speed indicator no longer displayed when disconnected
- [B29775](#): Ejecting device while in About menu no longer cause crash
- [B30000](#): Opening User Option when device unavailable no longer cause crash
- [B30057](#): Accessing "Messaging" while in Airplane Mode no longer cause crash
- [B30277](#): Fixed rare crash when resuming from hibernate state

## SIERRA WIRELESS, INC.

Document #:		Revision:	Build 3375	Page 14 of 19
-------------	--	-----------	------------	---------------

- [B30307](#): Usage History is now updated for CDMA connections
- [B29763](#): No longer display 'No SIM Inserted' after resuming from sleep
- [B30056](#): [MC7750] Improved SIM detection
- [B30065](#): [MC7750] Improved device detection across suspend/resume
- [B31127](#): Read SMS messages are now saved to the host
- [B30318](#): Connection button disabled after disconnecting
- [B31274](#): Sound is played during Connect/Disconnect/New SMS Message
- [B30047](#): Display appropriate error message when attempting to disconnect a connection initiated via Win7 MBB

### 2.10.3 Supported devices:

- Gobi 3000
- MC7700
- MC7710
- MC7750 (Evaluation purposes only)

### 2.10.4 Known Issues

- Device drivers are not included and must be installed separately
- Online Help localization incomplete
- Network selection and USB interface management not supported
- Advanced Help->About UI not supported
- DUN connections not supported
- Auto launch application on data connection not supported

## SIERRA WIRELESS, INC.

Document #:		Revision:	Build 3375	Page 15 of 19
-------------	--	-----------	------------	---------------

### 2.11 Build 2964

#### 2.11.1 Component List

Changes between this version and the previous one are highlighted in blue.

Description	Component	Revision
Watcher Main Application	Watcher.exe	12.0.1103.4
QMI API	GobiApi.dll	1.2.1103.2
CNS API	SwiApiInterfaceX.dll	11.3.1102.0
Card Detect Service	SwiCardDetect.exe	11.3.1102.0
Card Detect	SwiCardDetectX.dll	11.3.1102.0
Watcher UI	WaUI.dll	11.3.1103.0
QMI Plug-in	QmiPlugin.dll	12.0.1103.5
Watcher Helper Application	WaHelper.exe	11.3.1102.0
MSI Installer	*.msi	6.0.2964.0001
Watcher Predefined Profiles	Predefined_Profiles.xml	1.56
SWLogCollector	SWLogCollector.exe	B2958
AirCard Updates	TRUUpdater.exe	B2943

#### 2.11.2 Change Details

- GPS Monitor
- CDMA support (Sprint and Verizon)
  - Data sessions
  - Activation
- [B27599](#): AirCard Updates
- [B28091](#): Carrier selection
- [B28470](#): Watcher auto launch on device detection
- [B28584](#): Usage history
- [B28248](#): Manual network selection
- [B28592](#): Speed graph
- [B30134](#): Profile improvements
- [B30055](#): SIM status improvements
- [B30309](#): SMS improvements
- [B28237](#): APN Profile creation improvements
- [B28602](#): Revised online help
- [B28596](#): Main UI improvements
- [B27911](#): Device detection improvements
- [B27752](#): User option improvements
- [B27520](#): Suspend-resume improvements
- [B28007](#): Hibernate-resume improvements
- [B27921](#): Updated User Guide
- [B30533](#): Toggling auto connect functionality no longer causes Watcher to freeze

Copyright © 2011 - 2012 Sierra Wireless, Inc.

The contents of this page are subject to the confidentiality information on page one.

## SIERRA WIRELESS, INC.

Document #:		Revision:	Build 3375	Page 16 of 19
-------------	--	-----------	------------	---------------

- [B30532](#): Add option to disallow roaming
- [B28235](#): Synchronize with W\_DISABLE state
- [B30317](#): Boot loader version displayed in Help->About
- [B30049](#): Allow Watcher un-installation to occur even if Diagnostic Tool is running
- [B27613](#): Radio on/off state can be modified without a SIM
- [B27638](#): Radio on/off state correctly updated
- [B30288](#): Disable "To" button in SMS Send window (phonebook not supported)
- [B30076](#): Remove 'Enable keyboard' from user options
- [B30047](#): Display error message when attempting to end a data session established external to Watcher
- [B30053](#): Disabled Windows 7 MB option
- Removed MS-VPN from profile auto-launch options
- Removed driver installation menu item

### 2.11.3 Supported devices:

- Gobi 3000
- MC7700 (Evaluation purposes only)
- MC7750 (Evaluation purposes only)
- MC8790 (Evaluation purposes only)

### 2.11.4 Known Issues

- Device drivers are not included and must be installed separately
- Online Help localization incomplete
- Network selection and USB interface management not supported
- Advanced Help->About UI not supported
- DUN connections not supported
- Auto launch application on data connection not supported



## SIERRA WIRELESS, INC.

Document #:		Revision:	Build 3375	Page 17 of 19
-------------	--	-----------	------------	---------------

### 2.12 Build 2838

#### 2.12.1 Component List

Changes between this version and the previous one are highlighted in blue.

Description	Component	Revision
Watcher Main Application	Watcher.exe	0.10.12.0
QMI API	GobiApi.dll	1.2.7.0
API Interface	SwiApiInterfaceX.dll	10.11.0.0
API MUX	SwiApiMuxX.exe	10.11.0.0
Card Detect Service 32bit	SwiCardDetect.exe	10.12.0.0
Card Detect Service 64bit	SwiCardDetect64.exe	10.12.0.0
Card Detect	SwiCardDetectX.dll	10.12.0.0
String Resource	SwiStrRes.dll	10.11.00
AirCard Module	SwiAirCardLib.dll	0.10.12.0
QMI Module	SwiQmiModemLib.dll	0.10.12.0
CDMA	SwiCDMA.dll	10.11.0.0
Dialup	SwiDialup.dll	10.11.0.0
GSM	SwiGSM.dll	0.10.12.0
Phonebook UI	SwiPhonebkUI.dll	10.11.0.0
Skin UI	SwiSkinUI.dll	10.11.0.0
Skinned Extended UI	SwiSkXUI.dll	1.1.0.25
SMS	SwiSMS.dll	0.10.12.0
SMS UI	SwiSmsUI.dll	0.10.10.1
Theme Manager API	SwiTMApi.dll	10.9.0.0
Theme Manager	SwiTMApp.exe	10.9.0.0
Extended UI	SwiXUI.dll	10.11.0.0
Voice	SwiVoice.dll	10.8.0.0
Watcher UI	WaUI.dll	10.11.0.1
Wireless Service Manager	WirelessServiceMgr.dll	0.10.12.0
Watcher Helper Application	WaHelper.exe	10.11.0.0
MSI Installer	*.msi	6.0.2776.01
Watcher Predefined Profiles	Predefined_Profiles.xml	1.56
SWLogCollector	SWLogCollector.exe	B2747 R10.9.0.0

#### 2.12.2 Change Details

- Added data usage tracking
- Added SMS Outbox functionality
- [B27092](#): Device detection improvements
- [B27095](#): Profile improvements
- [B27096](#): General UI improvements
- [B27098](#): User option improvements
- [B27565](#): Byte counter information is now reported correctly

#### 2.12.3 Supported devices:

- Gobi 3000
- MC7750

Copyright © 2011 - 2012 Sierra Wireless, Inc.

The contents of this page are subject to the confidentiality information on page one.

Document #:		Revision:	Build 3375	Page 18 of 19
-------------	--	-----------	------------	---------------

- MC8790

#### **2.12.4 Known Issues**

- Network selection and USB interface management not supported
- Advanced Help->About UI not supported
- DUN connections not supported
- Auto launch on device power up not supported
- Speed graph not supported
- Autolaunch application on data connections not supported

### **2.13 Build 2805**

#### **2.13.1 Component List**

<b>Component</b>		<b>Revision</b>
Watcher Main Application	Watcher.exe	0.10.10.1
QMI API	GobiApi.dll	1.2.4.0
API Interface	SwiApiInterfaceX.dll	10.11.0.0
API MUX	SwiApiMuxX.exe	10.11.0.0
Card Detect Service 32bit	SwiCardDetect.exe	10.11.0.4
Card Detect Service 64bit	SwiCardDetect64.exe	10.11.0.4
Card Detect	SwiCardDetectX.dll	10.11.0.2
AirCard Module	SwiAirCardLib.dll	0.10.10.1
Wireless Service Manager	WirelessServiceMgr.dll	0.10.10.1
Watcher Helper Application	WaHelper.exe	10.11.0.0
MSI Installer	*.msi	6.0.2776.01
Watcher Predefined Profiles	Predefined_Profiles.xml	1.56
SWLogCollector	SWLogCollector.exe	B2747 R10.9.0.0

#### **2.13.2 Supported Devices**

- Gobi 3000
- MC7750
- MC8790

#### **2.13.3 Watcher Application**

- Supported functionality:
  - Airplane mode
  - Power management (suspend/hibernation/resume)
  - SIM lock (PIN1 only)
  - Options UI
  - Help->About UI
  - Reporting of serving network and signal strength
  - Data connectivity
  - Themes
  - Watcher auto-launch
  - SMS inbox functionality
  - Profile management

## SIERRA WIRELESS, INC.

Document #:		Revision:	Build 3375	Page 19 of 19
-------------	--	-----------	------------	---------------

### 2.13.4 Known Issues

- Drivers are not included and must be installed separately
- Network selection, USB interface management, and Data Usage Tracking UI not supported
- Advanced Help->About UI not supported
- SMS Outbox functionality not supported
- DUN not supported
- Autolaunch application on data connections not supported